Geotab Replacing a GO device in Geotab

Geotab offers an option to replace a current device with another. This feature maintains all existing data

such a trip histories, exceptions, engine data, ELD/Hour of Service data, and DVIR reports.

To replacing a device

To replace a device, a user must have the clearance Administer devices (delete/unplug/replace) or

Administer devices enabled.

1. Click the Vehicles & Assets option in the left menu (figure 1).

2. Select the vehicle by clicking the vehicle name in the list.

3. Scroll to the center of the Asset tab and find the Replace with new device button (figure 2).

4. Click the Replace with new device button located under the device serial number field (figure 3). Once the button is clicked a new window is displayed.

5. Enter the serial number for the NEW device in the Serial Number field (figure 4).6. Finally, click the OK button at near the top of the window and the change is complete.

Download Instructions

MY GEOTAB	r («)					? eron.iler@fleetistics.com			
a Search							Installation ~ Reports ~ + Asset ~			
Cashboard	Assets 1	Q Name, VIN, or serial number Filter by group	 ✓ Asset typ 	e ×	Powertrain and fuel type	🗸 All filters				
🖾 Мар	Bookmarks									
Productivity	+ 4	Offline O								
Compliance	+	Devices								
Safety	+	1-13 of 13 <								
3 Maintenance	+	□ ▼ Name	Current driver	License plate	Odometer (mi)	Comment				
3 Sustainability	+ I			License plate	000110101(010)					
23 People	+	El - BigTex Trailer Trailer, Fleetistics	-	-	971		:			
Add-Ins	+	EI - CubCadet (2) Fleetistics, Equipment	-	-	613	100 hours at time of install.	:			
Marketplace		EI - F450 (G09) Fleetistics, Vehicle, Diesel, D-T	-	-	43 275	Purchased new. 8.19.2022	:			
Support	+	EI - KUB - EXEC(1)			175		:			
System	+	Equipment, Fleetistics			175					
Settings		D-Training, Gasoline or Petrol, Vehicle,	-	-	9 760		1			
Audit Log ELD Info Config		EI - Sherp ATV Eron Group, Vehicle	-	-	0	-	:			
GoAnalytics		El - Sherp ATV PDQ Trailer Fleetistics, Trailer	-	-	0	-	:			
Registration cont	fig	Eron - PC			0		:			

Figure 2

Geotab

My geotab [®]			Groups filter All gr	oups selected			0	eron.iler@fleetistics.com fleetistics			
٩	Search	I.F.	Save Remove Cancel View	on map 🛛 😵 Personal Mode							
6	Dashboard 6	Assets	Asset EI - POR - (G	09)							
	Ш Мар 🛛										
⊕	Productivity	+ 🔺	Asset Health Audio feedback Data Sharing Rate plan Settings								
£	Compliance	+	ASSET INFORMATION			Asset Usage	Last 7 days				
00	Safety	+	Name/Description	EI - POR - (GO9)		e coursed 1266 dEmin e produce 06 dd	ania a talian Ob Eferia	→ ••⊙			
B	Maintenance	+	Current driver	Unknown driver		Stopped: 136h 45min Driving: 8h 46	Smin • Idling: Un Somin				
Ø	Sustainability	+ •	Current unver	C Assign driver		Last communicated: 04/15/24 09:26:38	3 am				
8	People	+		[+ Ennerta Elimente O	Map Sa	tellite			
r Ø	Maintenance	+ I	Asset type	Vehicle •		T Esporta Fitness					
2	People	+	Groups	Select groups Reset selection		~					
ప	Add-Ins	+		Vehicle Fleetistics × D-Training ×		Compton Place					
				Gasoline or Petrol ×							
90	Safety	+	Status groups	Select groups							
B	Maintenance	+		No Status Groups		Georgia 6					
Ø	Sustainability	+ •				16221 Compton Dr, Tampa, FL 33647, USA	We Map Data 100 m	trip history			
තී	People	+	VIN ①	WP18A2AY: Porsche Cayenne (2024)							
స	Add-Ins	+	License plate ①			Fuel Economy					
			License plate			Last 30 days 17.7 MPG (US)	Fuel 70% ful	10			
00	Safety	+	State/province								
Ş	Maintenance	+	Odometer 💿	9760	mi	Exceptions ->		Last 7 days			
Ø	Sustainability	+ •		(Time since last reported: 59 minutes)		Seat belt Device: Unauthorized Device Removal	x35 x1	î			
Ø	Sustainability	÷ U	Current engine hours	227 hours 42 m		Unauthorized Device Removal	x1 x1				
Ø	Sustainability	+ •	Device type	Version 9		Safety: Harsh cornering	x1	I			
Ø	Sustainability	÷ •				Hard Acceleration	x2	•			
00	People		Unplug device								
යි රූ	People Add-Ins	++	Current Status and Installation Info								
			Serial number 🛈	G98E211845F6 🧷 Replace with new device 🚺		~					
*	Marketplace	+	Device replacement required	No replacement required							
0 ©	Support System	++					Remember to add	d the new			
	Settings	Τ'	Device replacement status	Not applicable		device serial number decal to					
E	Audit Log ELD Info Config GoAnalytics Registration config		Comments				the door jam of th	ne vehicle.			

Unique solution ID: #1345 Author: n/a Last update: 2024-04-15 16:33